

SOW CHANGE PROPOSAL

SOW-02-832-1-08594A-2/4, Change 2

7 August 2001

STATEMENT OF WORK (SOW)
For the
Inspection and Repair Only As Necessary (IROAN)
Of the
Light Armored Vehicle (LAV-25)
NSN 2320-01-123-1602
SOW-02-832-1-08594A-2/4, Change 2

Change Paragraph 2.4:

Add new TM listing

To read:

TM 10367A-12&P

BG 10 Gun Barrel Bore Gauge (Draft)

Add new paragraph:

3.3.2.9

To read:

3.3.2.9 Brake drums shall not exceed .036 inches (.912mm) above the standard measurement as outlined in TM 08594A 34/9A Paragraph 13-3. Those drums exceeding .036 (.912mm) must be replaced.

Add new paragraph:

3.3.2.10

To read:

3.3.2.10 The Gun Barrel Bore Gauge (BG-10) will be used to inspect the M242 gun barrel. The barrel will be discarded when inspection process reveals three rejections between positions 9-16.

If approved, does this proposed change have the potential to have an impact on the cost or schedule?

* Yes _____ No _____ (Place an X in the appropriate block)

*Changes that have the potential to impact cost or schedule will be reviewed by Maintenance Directorate (MD) and an impact statement provided to LCMC. Changes that do not have the potential to impact cost or schedule may not be reviewed by MD.

Change Submitted by: SSST [Signature] (Name) 7 Aug 81 Date

Logistics Management Specialist (Title)

(Code 833-1)
MARCORSYSCOM, Albany, GA

Change Approved by: [Signature] (Name) 15 Aug 81 Date
Logistics Management Specialist

(Code 833-1)
MARCORSYSCOM, Albany, GA

Change Disapproved by: _____ (Name) _____ Date
Logistics Management Specialist

(Code _____)
MARCORSYSCOM, Albany, GA